




# Replaces Toro Groundsmaster 7210

## Parts

Zero-Turn Mower with 72in Deck - Model 30618

72in Rotary Mower - Model 30353



All original equipment manufacturers names and part numbers are used for identification purposes only, and we are in no way implying that our products are original equipment parts. Prices subject to change without notice.



# Replaces Toro Groundsmaster 7210 Parts

Zero-Turn Mower with 72in Deck - Model 30618  
72in Rotary Mower - Model 30353



| Item No                      | R&R Part No.        | OEM Part No.                                    | Description                                        | Qty Req | Order Quantity |
|------------------------------|---------------------|-------------------------------------------------|----------------------------------------------------|---------|----------------|
| <b>Belts</b>                 |                     |                                                 |                                                    |         |                |
| 20                           | <b>R110-9592</b>    | 110-9592                                        | Belt - V                                           | 1       |                |
| 21                           | <b>R110-9593</b>    | 110-9593                                        | Belt - V                                           | 1       |                |
| <b>Rotary Blades</b>         |                     |                                                 |                                                    |         |                |
| 31                           | <b>RRB1060-2500</b> | 112-9586-03                                     | Mower Blade - Low Lift 25.18 x 2.5in x 1/2 Mt Hole | 3       |                |
| <b>Other Parts Available</b> |                     |                                                 |                                                    |         |                |
| 70                           | <b>R104-3554</b>    | 104-3554                                        | Shaft - Spindle Assy.                              | 3       |                |
| 70                           | <b>R139-1044</b>    | 139-1044                                        | Shaft - Spindle Assy                               | 3       |                |
| 71                           | <b>R92-9800</b>     | 69-6950,<br>69-6980,<br>92-9800                 | Spacer - Spindle                                   | 3       |                |
| 71                           | <b>R138-6416</b>    | 138-6416                                        | Spacer - Spindle Shaft                             | 3       |                |
| 72                           | <b>R253-154</b>     | 253-154                                         | Seal - Spindle                                     | 6       |                |
| 73                           | <b>R104-3549</b>    | 104-3549                                        | Spacer Set - Spindle Bearing                       | 3       |                |
| 73                           | <b>R120-5577</b>    | 120-5577                                        | Bearing Spacer Set - Ground                        | 3       |                |
| 74                           | <b>R110-8297</b>    | 110-8297,<br>26-1830                            | Bearing Set w/Retaining Rings - Spindle            | 6       |                |
| 75                           | <b>R104-8322</b>    | 104-8322,<br>120-5576                           | Washer - Spindle Shaft Hardened                    | 3       |                |
| 76                           | <b>R32127-46</b>    | 32127-46,<br>3296-60                            | Locknut                                            | 3       |                |
| 77                           | <b>R104-8301</b>    | 104-8301,<br>104-9301,<br>109-6658,<br>133-7570 | Locknut - 3/8-16 Nylon Flanged                     | 29      |                |

All original equipment manufacturers names and part numbers are used for identification purposes only, and we are in no way implying that our products are original equipment parts. Prices subject to change without notice.



# Replaces Toro Groundsmaster 7210 Parts

Zero-Turn Mower with 72in Deck - Model 30618  
72in Rotary Mower - Model 30353



| Item No | R&R Part No.     | OEM Part No.                                                                                                | Description                       | Qty Req | Order Quantity |
|---------|------------------|-------------------------------------------------------------------------------------------------------------|-----------------------------------|---------|----------------|
| 77      | <b>R32128-19</b> | 104-8301,<br>104-9301,<br>32128-19                                                                          | Locknut - 3/8-16 Flanged Top Lock | 29      |                |
| 78      | <b>R3234-42</b>  | 3234-42                                                                                                     | Bolt - 3/8-16 x 1 Hx HD Fl        | 1       |                |
| 79      | <b>R68-6840</b>  | 68-6840                                                                                                     | Shaft - Roller                    | 1       |                |
| 80      | <b>R110-9596</b> | 110-9596,<br>132-9421                                                                                       | Pulley- Flat Idler                | 1       |                |
| 81      | <b>R3296-25</b>  | 30-3380,<br>32127-21,<br>32127-31,<br>3290-160,<br>3290-33,<br>3296-13,<br>3296-25,<br>3296-45,<br>329645   | Locknut - 1/2-13 Heavy ESNA       | 4       |                |
| 82      | <b>R325-17</b>   | 01-150-0640,<br>01-150-0850,<br>01-178-0832,<br>01-178-0836,<br>20-97-AGD,<br>325-17,<br>325-18,<br>48-9260 | Bolt - Hex Head                   | 2       |                |
| 83      | <b>R68-6710</b>  | 68-6710                                                                                                     | Roller - Rotary Deck              | 1       |                |
| 84      | <b>R29-4820</b>  | 29-4820                                                                                                     | Roller                            | 2       |                |
| 85      | <b>R104-3546</b> | 104-3546                                                                                                    | Pulley - Lower Driven             | 1       |                |
| 86      | <b>R104-3547</b> | 104-3547                                                                                                    | Pulley - Double Driven            | 1       |                |
| 87      | <b>R104-3548</b> | 104-3548                                                                                                    | Pulley - Higher Driven            | 1       |                |
| 88      | <b>R108-1924</b> | 108-1924                                                                                                    | Spacer-Idler                      | 2       |                |
| 89      | <b>R114-5680</b> | 114-5680                                                                                                    | Bushing - Flanged                 | 2       |                |

All original equipment manufacturers names and part numbers are used for identification purposes only, and we are in no way implying that our products are original equipment parts. Prices subject to change without notice.



# Replaces Toro Groundsmaster 7210 Parts

Zero-Turn Mower with 72in Deck - Model 30618  
72in Rotary Mower - Model 30353



| Item No | R&R Part No.        | OEM Part No.                                      | Description                                   | Qty Req | Order Quantity |
|---------|---------------------|---------------------------------------------------|-----------------------------------------------|---------|----------------|
| 90      | <b>R119-4548</b>    | 104-3530,<br>119-4548,<br>139-1037                | Double Driven Spindle Assy                    | 1       |                |
| 91      | <b>R119-4549</b>    | 104-3531,<br>119-4549,<br>139-1038                | High Driven Spindle Assy                      | 1       |                |
| 95      | <b>R119-4775</b>    | 119-4775                                          | Spindle Housing Assy                          | 1       |                |
| 93      | <b>R119-4776</b>    | 104-3532,<br>119-4776                             | Spindle Assy                                  | 1       |                |
| 94      | <b>R106-7159</b>    | 106-7159                                          | O-Ring                                        | 1       |                |
| 95      | <b>R302-60</b>      | 302-60                                            | Zerk - Grease 90 Deg.                         | 4       |                |
| 96      | <b>R72-9361</b>     | 27-1000,<br>27-1001,<br>72-9360,<br>72-9361       | Cup - Anti-Scalp                              | 3       |                |
| 97      | <b>R92-5816</b>     | 92-5816                                           | Bolt - Hex HD 1/2-20 x 2-1/4                  | 3       |                |
| 98      | <b>R110-9828</b>    | 110-9828                                          | Spring - Torsion                              | 2       |                |
| 99      | <b>R325-22</b>      | 01-150-0650,<br>01-178-0844,<br>325-21,<br>325-22 | Bolt - Hx HD 1/2-13 x 5 1/2                   | 2       |                |
| 100     | <b>R325-33</b>      | 325-33                                            | Bolt - Hx HD 1/2-13 x 6 1/2                   | 2       |                |
| 101     | <b>R93-4510</b>     | 93-4510                                           | Bushing                                       | 2       |                |
| 102     | <b>R108-1993</b>    | 108-1993                                          | Screw - 1/2-13 x 1 3/4 Button Socket Head Cap | 2       |                |
| 103     | <b>R100-3102</b>    | 100-3102                                          | Washer-Flat                                   | 1       |                |
| 104     | <b>R01-268-0160</b> | 01-268-0160                                       | Pulley - V Idler                              | 1       |                |
| 105     | <b>R114-8195</b>    | 114-8195,<br>R & R ONLY                           | Bolt- Ribbed Neck                             | 8       |                |

All original equipment manufacturers names and part numbers are used for identification purposes only, and we are in no way implying that our products are original equipment parts. Prices subject to change without notice.



# Replaces Toro Groundsmaster 7210 Parts

Zero-Turn Mower with 72in Deck - Model 30618  
72in Rotary Mower - Model 30353



| Item No | R&R Part No.        | OEM Part No.                                                                                                                                   | Description                 | Qty Req | Order Quantity |
|---------|---------------------|------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------|---------|----------------|
| 106     | <b>R110-0988</b>    | 110-0988                                                                                                                                       | Pad - Anti-Skid-Floor, Side | 1       |                |
| 107     | <b>R93-7818</b>     | 93-7818                                                                                                                                        | Decal - Blade Torque        | 2       |                |
| 108     | <b>R63-9750</b>     | 63-9750,<br>64-9750                                                                                                                            | Mount - Rubber              | 3       |                |
| 109     | <b>R302-5</b>       | 21-6010,<br>302-11,<br>302-37,<br>302-47,<br>302-5,<br>302-57,<br>302-58,<br>302-6,<br>31-0300,<br>32-9660,<br>60-0800,<br>62-3880,<br>92-4181 | Fitting - Grease            | 4       |                |
| 110     | <b>R93-6696</b>     | 93-6696                                                                                                                                        | Decal - Warning             | 3       |                |
| 111     | <b>R63-8410</b>     | 53-6380,<br>63-4810,<br>63-8410                                                                                                                | Washer - Isolator Bushing   | 3       |                |
| 112     | <b>R112-1625</b>    | 112-1625                                                                                                                                       | Pull Link Assy              | 2       |                |
| 113     | <b>R107-2328</b>    | 107-2328                                                                                                                                       | Bushing                     | 1       |                |
| 114     | <b>R120-5570</b>    | 112-1622,<br>120-5570                                                                                                                          | Pin - Retainer              | 2       |                |
| 115     | <b>R700414</b>      | 302-11,<br>302-19,<br>302-4,<br>32-8170                                                                                                        | Zerk - Grease 1/4-28 45 Deg | 4       |                |
| 116     | <b>R110-5070</b>    | 110-5070                                                                                                                                       | Bumper - Neoprene           | 2       |                |
| 117     | <b>R120-6603-03</b> | 120-6603-03                                                                                                                                    | Ring - Doubler              | 3       |                |
| 118     | <b>R108-1921</b>    | 108-1921                                                                                                                                       | Torsion Spring - Idler      | 2       |                |

All original equipment manufacturers names and part numbers are used for identification purposes only, and we are in no way implying that our products are original equipment parts. Prices subject to change without notice.



# Replaces Toro Groundsmaster 7210 Parts

Zero-Turn Mower with 72in Deck - Model 30618  
72in Rotary Mower - Model 30353



| Item No | R&R Part No.     | OEM Part No.                                                                                   | Description                    | Qty Req | Order Quantity |
|---------|------------------|------------------------------------------------------------------------------------------------|--------------------------------|---------|----------------|
| 119     | <b>R115-1429</b> | 115-1429                                                                                       | Yoke - Clevis                  | 4       |                |
| 120     | <b>R3296-29</b>  | 1-804256,<br>3290-357,<br>3296-29,<br>915662P                                                  | Locknut - 5/16-18 ESNA         | 8       |                |
| 120     | <b>R3296-39</b>  | 32127-25,<br>32128-36,<br>3290-357,<br>3296-17,<br>3296-22,<br>3296-39,<br>915663P,<br>99-7443 | Locknut - 3/8-16 Nylon         | 8       |                |
| 120     | <b>R32128-43</b> | 30-8990,<br>32128-43,<br>3290-357                                                              | Nut - Flanged Whiz - 3/8-16    | 8       |                |
| 120     | <b>R3218-3</b>   | 01-191-0616,<br>22-13-AJKD,<br>3218-3,<br>915236P                                              | Nut - 3/8-16 Jam               | 4       |                |
| 121     | <b>R3231-7</b>   | 3231-33,<br>3231-7                                                                             | Bolt - Carriage 3/8-16 x 2-1/4 | 4       |                |
| 122     | <b>R325-14</b>   | 01-150-1720,<br>01-178-0828,<br>20-95-AD,<br>20-95-AGD,<br>3226-9,<br>325-14                   | Bolt - Hex HD 1/2-13 x 3-1/2   | 1       |                |
| 123     | <b>R443818</b>   | 01-191-0813,<br>3218-18,<br>3218-5                                                             | Nut - 1/2-13 Hex Jam Zinc      | 2       |                |
| 124     | <b>R32120-84</b> | 32120-84                                                                                       | Ring - Snap                    | 2       |                |

All original equipment manufacturers names and part numbers are used for identification purposes only, and we are in no way implying that our products are original equipment parts. Prices subject to change without notice.



# Replaces Toro Groundsmaster 7210 Parts



Zero-Turn Mower with 72in Deck - Model 30618  
72in Rotary Mower - Model 30353

| Item No | R&R Part No.    | OEM Part No.                                                                                                          | Description                      | Qty Req | Order Quantity |
|---------|-----------------|-----------------------------------------------------------------------------------------------------------------------|----------------------------------|---------|----------------|
| 125     | <b>R101526</b>  | 01-150-0970,<br>01-178-0620,<br>20-53-AGD,<br>321-11,<br>3224-8,<br>323-11,<br>323-12,<br>323-31,<br>323-4,<br>323-47 | Bolt - Hex HD 3/8-16 x 2-1/2 GR5 | 4       |                |
| 125     | <b>R323-11</b>  | 01-150-1440,<br>01-178-0618,<br>20-52-AD,<br>3224-7,<br>323-11                                                        | Bolt - 3/8-16 x 2 1/4 GR5        | 4       |                |
| 125     | <b>R400120</b>  | 01-150-0990,<br>01-178-0416,<br>02-150-0990,<br>321-11,<br>3222-4,<br>33114-010,<br>33114-060,<br>513327,<br>908470   | Bolt - Hex HD 1/4-20 x 2         | 4       |                |
| 125     | <b>R400258</b>  | 01-150-0800,<br>01-178-0600,<br>01-178-0606,<br>20-45-AD,<br>31-0200,<br>31-9910,<br>3224-1,<br>323-4                 | Bolt - Hex HD 3/8-16 x 3/4       | 4       |                |
| 126     | <b>R463017</b>  | 2119-561,<br>31-4400,<br>3257-5                                                                                       | Key - Woodruff                   | 1       |                |
| 127     | <b>R3253-21</b> | 215-51,<br>30-8470,<br>3253-21,<br>Jul-12                                                                             | Washer - Lock 3/8                | 4       |                |

All original equipment manufacturers names and part numbers are used for identification purposes only, and we are in no way implying that our products are original equipment parts. Prices subject to change without notice.



# Replaces Toro Groundsmaster 7210 Parts



*Zero-Turn Mower with 72in Deck - Model 30618*  
*72in Rotary Mower - Model 30353*

| Item No | R&R Part No.     | OEM Part No.                        | Description                      | Qty Req | Order Quantity |
|---------|------------------|-------------------------------------|----------------------------------|---------|----------------|
| 128     | <b>R104-8300</b> | 104-8300,<br>104-8300 ,<br>119-4041 | Locknut - 5/16-18 Flanged Y/Zinc | 2       |                |

All original equipment manufacturers names and part numbers are used for identification purposes only, and we are in no way implying that our products are original equipment parts. Prices subject to change without notice.