


Replaces Toro Greensmaster 3150-Q Parts



SPA Cutting Unit - Models 04445, 04448 & 04450 Minuteman Roller System





Item R&R

Replaces Toro Greensmaster 3150-Q Parts



Order

Qty

SPA Cutting Unit - Models 04445, 04448 & 04450 Minuteman Roller System

OEM

	Part No.	Part No.	Description	Req	Quantity
Com	olete Minutemai	n Roller Systems	·		
1	RMT8001		Minuteman Front Grooved Roller System	0	
	Detail Descriptio	on: Complete roller syst	ems include roller and two brackets with bearings.	<i>:</i>	
Minu	teman Rollers O	nly			
2	RM513		Minuteman Grooved Roller Only	0	
	Detail Description: Use with Minuteman Roller Bracket System Only:				
Othe	r Parts Available	2			
3	RT821		Bracket Assy - Front LH/RH	2	
	Detail Description: Includes RT8210 Bearing & Locking Collar, RMM606 Washer, R3219-5 Nut & RMM607 Screw:				
4	RMMB157		Bearing w/Locking Collar	2	
5	RT8210		Block - Height Adj	2	
6	RMM606		Washer - Lock 3/8 Zinc Internal Tooth	2	
7	R3219-5	01-188-0820, 22-15-BJD, 22-15-BJKD, 3219-5	Nut - 1/2-20	4	
8	RMM607	01-158-0610, 01-191-0820, 21-3900, 3220-5, 45-0170, 5/1/3220	Nut - Jam 1/2-20 Zinc	2	
9	RMM608		Screw - 8-32 x 5/16 SS Socket Head	2	
10	RMM3		End Hub - 7/8 ID	2	
11	RT821P		Plate - For RT821 Bracket	2	
12	RT821B		Ball - For RT821 Bracket	2	

All original equipment manufacturers names and part numbers are used for identification purposes only, and we are in no way implying that our products are original equipment parts. Prices subject to change without notice.



Replaces Toro Greensmaster 3150-Q Parts



SPA Cutting Unit - Models 04445, 04448 & 04450 Minuteman Roller System