



Replaces Toro Workman 2100 Parts

Traction Unit - Model 07253

Steering & Controls



All original equipment manufacturers names and part numbers are used for identification purposes only, and we are in no way implying that our products are original equipment parts. Prices subject to change without notice.



Replaces Toro Workman 2100 Parts

Traction Unit - Model 07253

Steering & Controls



Item No	R&R Part No.	OEM Part No.	Description	Qty Req	Order Quantity
---------	--------------	--------------	-------------	---------	----------------

Filters

10	R108-3811	108-3811	Element - Air Cleaner	1	
10	R93-2195	93-2195	Baldwin Air Filter	1	
10	RRF10125	108-3808, 93-2195	SilverGuard Air Filter	1	

Guages and Controls

30	R114-3315	114-3315	Solenoid -12 Vdc	1	
31	R94-4208	94-4208	Hourmeter	1	
32	R95-8999	95-8999	Switch - Headlight	1	
33	R80-9330	80-9330	Alarm - Audio	1	
34	R151541	R&R ON, LY	Delta Seat Switch - Twist Mount 1 Pole Normally Open	1	

Other Parts Available

70	RMXB180GY	106-6672, 112-2923, 119-8829, 133-0577	Milsco Seat XB180 - Grey	1	
----	------------------	---	--------------------------	---	--

*Detail Description: The Milsco XB180 bucket seat is designed with a sturdy vacuum formed waterproof vinyl cover that will not crack or peel. Ergonomic foam cushions ensure operator comfort. Features a durable blow molded plastic frame. Allows for an operator presence switch. Central drain hole prevents water build-up. 19 inch high-back seat will replace both original 16in and 19in high-back seats. Seat: 18.75in W x 18.8in H. Grey. Made in U.S.A.
Please note: Due to excessive air freight charges, this item will be shipped ground freight.:*

71	R98-1471	93-5212, 94-3500, 98-1471	Steering Wheel Assy - 14 in Incl Cap	1	
72	R98-1468	98-1468	Cap - 14" Steering Wheel	1	
73	R95-5806	95-5806	Bracket-Mounting	1	
74	R99-7420	100-8493, 99-7420	Plug-Hole	1	

All original equipment manufacturers names and part numbers are used for identification purposes only, and we are in no way implying that our products are original equipment parts. Prices subject to change without notice.



Replaces Toro Workman 2100 Parts

Traction Unit - Model 07253

Steering & Controls



Item No	R&R Part No.	OEM Part No.	Description	Qty Req	Order Quantity
75	R104-8300	104-8300, 104-8300 , 119-4041	Locknut - 5/16-18 Flanged Y/Zinc	2	
76	R92-5018-03	92-5018, 92-5018-03	Clamp-Battery	1	
77	R87-9400	104-0498, 87-9400	Valve - Vacuator	1	
78	R2412-133	01-651-0160, 2412-133	Clamp	1	
79	R3234-11	3234-11	Bolt - Hex Washer HD	1	
80	R150848	100-4928, 106-7848, 110-0413, 110-9720, 95-8910	Belt-Seat	1	
81	R3274-105	3274-105	Screw - Button HD Soc Cap	1	

All original equipment manufacturers names and part numbers are used for identification purposes only, and we are in no way implying that our products are original equipment parts. Prices subject to change without notice.